

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure Jun 22, 2017		Time(s): 7:30	am - 12:00 am					
Building(s) #1 DENTAL SCIENCE BUILDING (DSB) #2 Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: DSB Roof L								
Service to be #1 Hazardous Exhaust #2 #3 #4 Description/Reason for Project: Access air conditioning unit on roof L that is not working. See attached list for affected exhaust								
equester: Bob Pickard Date of Request: Jun 21, 2017								
Supervising Tradesperson: Bob Pickard Unit: Refrigeration								
Trade Supervisor: Ken Hill Unit: Refrigeration Date:Jun 21, 2017								
Contractor: Phone #								
Coordinator/Project Manager: Bob Pickard Phone # Date:Jun 21, 2017								
Reviewed by Trade Supervisor(s)/Shop(s) Affected:								
Name: WES Control	Date: Jun 21, 2017	7 Name: E	Name: Electrical Mechanical Shop Date:		Date:			
Signature/ Stamp:		Signature/			Jun 21, 2017			
Name:	Date:	Principal Occu	Principal Occupants:					
Signature/		Name:			Date:			
Stamp:		Name:		Ext.	Date:			
Name:	Date:	Name:		Ext.	Date:			
Signature/ Stamp:		Name:	Name: Ext. Date: Approval to Proceed: Date:					
Name:	Date:							
Signature/ Stamp:			APPROVED By Andrew Merucci (amerucci@uwo.ca) at 1:31 pm, Jun 21, 2017					
Notes:								

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED: 2013 / 04 / 30

BUILDING DENTAL SCIENCE

SYSTEM	ROOM #	FAN	OUTLET	USE	NOTES
#		LOCATION	LOCATION		
-027-	0033,0034	L	L	3 Fume Cabinets	Installed 2008
-081-	0142	L	L	Old Box fan on roof L – switch tagged off in	
				room0142	
-086	0015	L	L	Fume Cab	New in 2003
-092-	0019	L	L	Fume Cab	
-094	0021	L	L	Fume Cab	