



Notice of Service Interruption/Area Closure
Western University
Facilities Management
Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail

Print Form

Date of Interruption/Closure

Time(s):

REVISED

3:31 pm, Mar 27, 2018

Building(s) #1
Affected: #3

#2

#4

Areas/Rooms Affected Alternate Route/Service:

Rooms with equipment exhausting to Hazardous Roof L. See attached list.

Service to be interrupted: #1
#3

#2

#4

Description/Reason for Project:

Review of Roof L condition.

Requester:

Date of Request:

Supervising Tradesperson:

Unit:

Trade Manager:

Unit:

Date:

Contractor:

Phone #

Coordinator/Project Manager:

Phone #

Date:

Reviewed by Trade Manager(s)/Shop(s) Affected:

Name:

Date:

Name:

Date:

Signature/
Stamp:

APPROVED

By spepper (spepper@uwo.ca) at 3:18 pm, Mar 21, 2018

Signature/
Stamp:

REVIEWED

By Wayne Drummond (ppdwad@uwo.ca) at 2:10 pm, Mar 21, 2018

Name:

Date:

Principal Occupants:

Signature/
Stamp:

Name:

Ext.

Date:

Name:

Name:

Ext.

Date:

Name:

Name:

Ext.

Date:

Name:

Name:

Ext.

Date:

Name:

Date:

Signature/
Stamp:

APPROVED

By Dan Trudgeon (dtrudgeo@uwo.ca) at 3:29 pm, Mar 21, 2018

Notes:

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING	DENTAL SCIENCE
----------	----------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
-027-	0033,0034	L	L	3 Fume Cabinets	Installed 2008
-081-	0142	L	L	Old Box fan on roof L – switch tagged off in room0142	
-086	0015	L	L	Fume Cab	New in 2003
-094	0021	L	L	Fume Cab	