

## Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/C	Closure <b>May 19, 2016</b>	<b>REVISED</b> 11:15 am, Apr 26, 2016	Time(s):	8:00 am - 3:00 pm			
Affected: #3	EALTH SC ADDITION (HSA)	ce:	#2 DE	ENTAL SCIENCE BUILDING (DSI	B) Roof C		
Labs and areas served by Hazardous Exhaust fans. See attached list.							
interrupted: #3	Hazardous Exhaust		#2				
Description/Reason for Project:  Down for maintenance on exhaust systems.							
Requester: Steve	Requester: Steve MacKay Date of Request: Apr 20, 2016						
Supervising Trade	esperson:		Unit:				
Trade Supervisor: Unit: Date:				Date:			
Contractor:				Phone #			
Coordinator/Project M	anager: Steve MacKay			Phone # 88764		Date:	
Reviewed by Trade Su	pervisor(s)/Shop(s) Affected:						
Name:	WES Control	Date: Apr 20, 201	16 Name:			Date:	
Signature/ Stamp:			Signature Stamp:	REVIEWED  By Wayne Drummond (ppdwad	@uwo.ca) at 2:34	pm, Apr 20, 2016	
Name:		Date:	Principal	Occupants:			
Signature/			Name:	Occupants.	Ext.	Date:	
Stamp:			Name:		Ext.	Date:	
Name:		Date:	Name:		Ext.	Date:	
Signature/			Name:		Ext.	Date:	
Stamp:				Approval to Proceed		Date:	
Name:		Date:	APP	ROVED			
Signature/ Stamp:  By Dan Trudgeon (dtrudgeo@uwo.ca) at 11:03 am, Apr 25, 2016							
Notes: Could trigg	er alarms at fume hoods f	for low flow.					

## **HAZARDOUS EXHAUST SYSTEMS INVENTORY**

## **LAST UPDATED: 2013 / 04 / 30**

BUILDING DENTAL SCIENCE

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
-035-	2005	С	С	ELEPHANT	
				TRUNKS	
				PNL5P #3	
-036-	2005	С	С	ELEPHANT	
				TRUNKS	
				PNL5P #6	
-037-	2010B	С	С	DOUBLE Fume	
				Cab	
				PNL 5P #14	
-038-	2011	С	С	FUME CAB	PNL 5P #21
-039-	2011?	С	С	NOT SURE!	SHUTDOWN MAY6TH 2014.
-040-	2003	С	С	Fume Cab	
-042-	3003D	С	С	Fume Cab	
-044-	3003	С	С	Fume Cab	
-045-	3004	С	С	Fume Cab	
-046-	3004	С	С	Fume Cab	
-047-	3004	С	С	Fume Cab	
-049-	3005B	С	С	Fume Cab	
-051-	2006	С	С	Fume Cab	OUT OF SERVICE
-052-	3006B	С	С	Fume Cab	
-062-	4011	С	С	Fume Cab	
-064-	4014	С	С	Hood	
-065-	4015	С	С	Fume Cab	
-078-	4010	С	С	Fume Cab	FC removed from rm 4009

GREEN HIGHLIGHT – INDICATES NON HAZARDOUS FAN

ORANGE FILL – INDICATES CHANGES HAVE BEEN MADE, INFO MAY BE INCORRECT OR MISSING.

-039- FAN WAS STILL RUNNING. WE SHUT IT DOWN ON MAY  $6^{\text{TH}}$  2014. WAITING TO SEE IF ANYONE REPORTS ANYTHING OFF. MAY BE CAPPED IN CEILING. WILL UPDATE WHEN WE HEAR ANYTHING. - CV

HSA FUME HOOD CONTACT INFO						
ROOM #	FUME CAB / FAN # CONTACT NAME		EXTENSION #			
H202	F 002	BRUCE ARPPE	X86646			
H216	F 003	BRUCE ARPPE OR G WAGNER	X86646/83966			
H301F	F 006	DR. KERFOOT	X82329			
H406	F 012	DR. CHAKRABORTY	X88704			
H408	F 007	DR. CHAKRABORTY	X88704			
H415	F013	DR. M DARLING	X86399			
H418	F 008,009	DR. T. DALEY	X86405			