



**Notice of Service Interruption/Area Closure**  
**Western University**  
**Facilities Management**  
**Client Services 519-661-3304 (fmhelp@uwo.ca)**

Submit by E-mail

Print Form

Date of Interruption/Closure Wed. Dec. 10th 2014

Time(s): 8:00 am ---- 5:00 pm

Building(s) #1 south valley at end of Huron Drive

#2

Affected:

#3

#4

Areas/Rooms Affected Alternate Route/Service:

grass area, well off the road and parking lot access. see attached plan for details

Service to be interrupted: #1 grass area as above

#2

#3

#4

Description/Reason for Project:

Hydro Vac excavation by City of London / Stantec / CC Dance for exploratory work on buried services in the area of future city watermain work in 2016.

Requester: Stantec Engineering Ltd - Simon Jeater

Date of Request: Dec 4, 2014

Supervising Tradesperson:

Unit:

Trade Supervisor:

Unit:

Date:

Contractor: Stantec Engineering Ltd / CC Dance Ltd - Simon Jeater - cell # ---->

Phone # +1 (519) 494-0124

Coordinator/Project Manager: M.DeJager

Phone # 88737

Date: Dec 4, 2014

Reviewed by Trade Supervisor(s)/Shop(s) Affected:

Name:

Date:

Name:

Date:

Signature/  
Stamp:

Signature/  
Stamp:

Reviewed by:

Principal Occupants:

Name:

Mike DeJager

Date: Dec 4, 2014

Name:

Ext.

Date:

Name:

Ext.

Date:

Name:

Ext.

Date:

Name:

Ext.

Date:

Approval to Proceed:

Date:


Approval to Proceed:

Date:

**APPROVED**

**By Andrew at 9:02 am, Dec 05, 2014**

Notes: locates complete. no assistance from FM required. site will be restored at the end of the day.



BOUNDARY LAYER  
WIND TUNNEL

THOMPSON  
ENGINEERING  
BUILDING

HAZARDOUS MATERIAL  
STORAGE COMPOUND

THOMPSON  
RECREATION AND  
ATHLETIC CENTRE

WESTERN STUDENT  
RECREATION CENTRE

PHILLIP AZIZ AVE.

HURON FLATS  
PARKING  
LOT

FIELD

AREA OF  
HYDROVAC  
FROM 8:00AM -  
5:00PM

BIKE