

Notice of Service Interruption/Area Closure Western University Facilities Management

Service Centre 519-661-3304 (fmhelp@uwo.ca)					
Western UNIVERSITY CANADA	010 001 000	(IIIII)	-	Submit by E-	mail Print Form
Date of Interruption/Closure Dec 12, 2014	Ti	me(s):	l0am -12pm		
Building(s) #1 Medical Sciences Building (MSB) #2 Affected: #3 #4 #4 Areas/Rooms Affected Alternate Route/Service: corridor TA 600. Outside of room 614. Corridor is not in use when I reviewed the job. Below. TA. 501 outside room 519, 520. A spotter will be below in ceiling.					
Service to be #1 Corridor #2 #2 #4 Description/Reason for Project: Core drill concrete slab for new drain required for drench shower					
Requester: Randy Regier			Date of Requ	nest: Dec 10, 20	014
Supervising Tradesperson: Dave Mains Unit:					
Trade Supervisor: Randy Regier		Unit:			Date:
Contractor:			Phone #		
Coordinator/Project Manager:			Phone #		Date:
Reviewed by Trade Supervisor(s)/Shop(s) Affected:					
Name: Da	ate:	Name:			Date:
Signature/ Stamp:		Signature, Stamp:	/		
Reviewed by: Principal Occupants:					
Name: Date	te:	Name: Kevi	n Inchley	Ext.	Date:
e:		Name:		Ext.	Date:
Signature/ Stamp:		Name:		Ext.	Date:
			. s. [LAC.	Dute.
Approval to Proceed: Approval to Proceed: Date: Approval to Proceed: Date: APPROVED By Dan Trudgeon (fminterr@uwo.ca) at 4:16 pm, Dec 11, 2014					
Notes: The drilling is noisy at the point of cont	act.				