



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

## WORKPLACE TASK TO BE ANALYSED

Locates

## DEPARTMENT

Facilities Management

## WESTERN JOB CLASSIFICATION\*

Electrician

## REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

safety glasses, safety footwear, high visibility vest, **ladder, hat, sun block, maintenance hole lid lifter**

## WESTERN HAZARD CATEGORY\*

Energy/Worksite Hazards

## HAZARD TYPE\*

Electricity/Traffic, Slips/Trips/Falls

## LOSS POTENTIAL RATING\*

Moderate

\*refer to Stantec Specific Job Report

## DATE:

March 17, 2021

## WRITTEN BY:

Dave Ostrom

## REVIEWED BY:

Electrical/Controls Shop

## MGMT APPROVAL:

Ken Gee

## SEQUENCE OF TASK

## POTENTIAL HAZARDS

## ACTION OR PROCEDURE

Assess work site	Traffic on roads, live electrical lines, <b>slip, trip, fall from height, UV exposure</b>	<b>WP-41</b> Safety cones, lock-out tag-out, <b>Second person as spotter in high traffic areas, sun block, hat</b>
<b>Removing maintenance hole covers when needed, Pre-use inspection of lid lifter</b>	<b>strain</b>	<b>Pre-use Inspection, Materials handling training</b>
<b>Prepare conductor to be located</b>	<b>Shock</b>	<b>Meter, Class zero gloves, Lock Out Tag out</b>
Set up transmitter	Trip hazard	Keep transmitter and ground wire away from side walks or pedestrian paths if possible
Clean up tools from work site		