

JOB HAZARD ANALYSIS - Task Specific

		NEW	X REVISED
WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD C.	WESTERN HAZARD CATEGORY*	
Waste Compactor Operation	Ergonomic/Worksite I	Ergonomic/Worksite Hazards	
DEPARTMENT	HAZARD TYPE*	I LHAZARD TYPE*	
Facilities Management	Pinch Points	Pinch Points	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RA	LOSS POTENTIAL RATING*	
Caretaker	Moderate	Moderate	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Speci	*refer to Stantec Specific Job Report	
Safety shoes, eye protection, mask, kevlar/canvas gloves			Chris Bumbacco
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDUR	RE
Assess and inspect equipment, controls and environement	a) Personal safety b) Back injury, overexertion strain c) Slip, trip, fall d) Exposure to dust and particulate,	 a) Proper personnel Protective equipment to be worn where applicable. b) Using ergonomic lifting considerations while lifting, bending twisting and while removing any chute blockages c) Safely ensure footing and body position for awareness of slip, trip or fall, d) Avoid spillage when disposing of waste, Also see any equipment manuals or labeling per Occupational Health and Safety and Caretaking manual. 	
Assign appropriate staff	Overexertion strain injuries	job requirements	Supervisor organize crew to uired as to safe ergonomic

Removal of large debris, articles, broken glass when chutes are plugged	a) Lacerations and abrasions	a) Ensure safe operation and operator safety by ensure all guards, safety devices, controls shut offs are in place when chute blockages are cleared. Wear gloves and masks when appropriate for removal of any visible large or broken glass articles and hazardous debris. Use pole or other tools to remove blockages to avoid arm or extended reach injuries. Never compact waste with hand or foot or other object. Never unload waste into another container by hand to avoid lacerations, abrasions, exposure etc.
	b) Repetitive strain, back injury	b) Use proper body mechanics while bending to pick up debris. Alternate duties when and where possible. Excessively full or overweight garbage bins are to be a two person operation utilizing another person to assist in removing the bin safely in collection area. Never compact waste with hand or foot or other object.
	c) Lacerations, abrasions, exposure, etc.	c) Never unload waste into another container by hand to avoid lacerations, abrasions, exposure, etc.
Proceed with removal of waste from area(s)	a) Over exertion strain injury	a) Avoid heavy lifting by ensuring garbage cans are of safe weight to be removed. Lift safely away from body with extended arms to avoid contact with sharp objects.
	b) Slip, trip, fall	b) Staff to watch proper footing. Observe pedestrian traffic around them with caution to work environment and awareness for slip and trip hazards (eg. Cord locations, furniture, drawers, obstructions).
	c) Exposure to particulate or debris	c) Follow appropriate directions for potential exposure to particulate, which will require eye protection and mask. Use bin transportation device (ie. cart/caddy) as required and according to instructions.
Troubleshooting		Escalate operational issues to trades as required.