



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal Installation of Doors

WESTERN HAZARD CATEGORY*

WorkSite Hazards

DATE:

April 5, 2006

DEPARTMENT

Facilities Management

HAZARD TYPE*

Slips/Trips/Falls, Working at Heights, Protruding/Sharp Objects

WRITTEN BY:

Ted Chelchowski

WESTERN JOB CLASSIFICATION*

Locksmith

LOSS POTENTIAL RATING*

Moderate

REVIEWED BY:

Ted Chelchowski

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

*refer to Stantec Specific Job Report

MGMT APPROVAL:

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Set up (ladder)	Slip weight	Attend Ladder Safety Seminar
Remove & reinstall	Sharp, projectile	Follow Work Area Protection Policy WP-41 (see attached policy)
Take down (ladder)	Tempered glass	Wear PPE
	Fall	Request the help of another staff member if necessary