



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Building flashing installation

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (ACMF)

**WESTERN HAZARD CATEGORY\***

Worksite Hazards

**HAZARD TYPE\***

Working at Heights, Working Alone

**LOSS POTENTIAL RATING\***

High

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Hearing protection (I.R.), harness/lifeline (I.R.), knee pads, appropriate clothing, gloves, grade 1 safety footwear, safety glasses/goggles

\*refer to Stantec Specific Job Report

**MGMT APPROVAL:**

Ken Hill

**SEQUENCE OF TASK**

**POTENTIAL HAZARDS**

**ACTION OR PROCEDURE**

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Prepare installation site	Roof stone, fall, position, sharp material, trip/slip	Shut down notice if hazardous roof
Cut/bend material as required, install/secure flashing, seal as required	Struck by, insect bite, UV, contact burn, hand tools, cold, working alone, chemical exposure	PPE, WHMIS, appropriate clothing, assistance, sun block/insect repellent
		Work by trained/licensed mechanic.
*I.R. if required		*Required safe use of hand/power tools