



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Building flashing installation

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (ACMF)

WESTERN HAZARD CATEGORY*

Worksite Hazards

HAZARD TYPE*

Working at Heights, Working Alone

LOSS POTENTIAL RATING*

High

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Hearing protection (I.R.), harness/lifeline (I.R.), knee pads, appropriate clothing, gloves, grade 1 safety footwear, safety glasses/goggles

*refer to Stantec Specific Job Report

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Prepare installation site	Roof stone, fall, position, sharp material, trip/slip	Shut down notice if hazardous roof
Cut/bend material as required, install/secure flashing, seal as required	Struck by, insect bite, UV, contact burn, hand tools, cold, working alone, chemical exposure	PPE, WHMIS, appropriate clothing, assistance, sun block/insect repellent
		Work by trained/licensed mechanic.
*I.R. if required		*Required safe use of hand/power tools