



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Clean plugged drains/traps

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (plumber, steamfitter)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Protective clothing, gloves, knee pads/kneeling pad. grade 1 safety footwear, safety glasses/splash goggles

**WESTERN HAZARD CATEGORY\***

Chemical/ Ergonomic hazards

**HAZARD TYPE\***

Other liquids/ Awkward, Static Posture

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

Plumbing/Fitting Shop

**MGMT APPROVAL:**

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Place bucket under trap, remove clean out cap/plug or trap or tailpiece	Chemical contact	P.P.E. ,clean floor in area
Drain liquid/remove glassware, etc., take sample (I.R.), have tested (I.R.)	HBBF, cut	Use caution to open drain and remove contents
Dispose of material safely.	Puncture	Work by experienced/licensed trade
Replace components, clean area as needed	Inhalation	Inoculations to protect against infectious agents
	Struck against	
	Position	