



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Cleaning of Fresh Air Intake, coils, louvres, grilles

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (ACMF)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Respiratory protection (I.R.), grade 1 safety footwear, safety glasses/goggles, protective clothing, gloves

**WESTERN HAZARD CATEGORY\***

WorkSite/ Chemical Hazards

**HAZARD TYPE\***

Slips/Trips/Falls / Particulates

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Air compressor on site (I.R.)	Inhalation	PPE, good portable light, WHMIS
Shut down unit, lock-out/tag-out (I.R.)	Sharp material, projectile	Equipment use by manufacturers instructions. Inform occupants as required.
Use required equipment to clean components	Trip, fall	GFCI outlet, if wet location
Cover equipment/ furnishings.	Poor light	Proper ladder use and UV protection
Clean work area as required	Struck against	
	Burn	
*I.R. If required		