

x REVISED

NEW

JOB HAZARD ANALYSIS - Task Specific

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CA	WESTERN HAZARD CATEGORY* DATE:	
Equipment assisted lifting (of units/components)	WorkSite/ Ergonomic	WorkSite/ Ergonomic Hazards	
DEPARTMENT	_J L L L WR		WRITTEN BY:
Facilities Management	Struck by, Sharp Objects/ Awkward posture, weight		Ken Hill
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT	LOSS POTENTIAL RATING* REVIEWED BY:	
Mechanical Trades (All)	Moderate	Moderate ACMF Sh	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specif	*refer to Stantec Specific Job Report MGMT APPRO\	
Hard hat (I.R.), appropriate clothing, hearing protection (I.R.), gloves, grade 1	safety footwear, safety glasses	s/goggles	Ken Hill
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE	
Set up lifting equipment	Position, sharp material, weight	PPE, follow manufacturer's instructions, ensure equipment safe/level footing	
Post/restrict area, prepare base, lift unit as required, dismantle equipment		Use slings/come-a-longs/electric hoists/chain falls as required	
		Inspect slings/come-a-longs/electic hoists/ chain falls prior to use for any visible damage	
Reverse procedure for removal		Job pre-planning, verbal communication	
		Confirm equipment capacity and unit weight.	
		Work/direction by trained/ licensed trade	

*Required safe use of

.R. if required	Power/hand tools	