



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Refill of chlorine solution tank

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Plumber

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety glasses/shield/ respiratory protection, grade 1 safety foot wear, neoprene gloves

**WESTERN HAZARD CATEGORY\***

Chemical Hazards

**HAZARD TYPE\***

Irritant

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

Plumbing/Fitting Shop

**MGMT APPROVAL:**

Dan Gyetvai

**SEQUENCE OF TASK**

**POTENTIAL HAZARDS**

**ACTION OR PROCEDURE**

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
1. Add total volume of bleach specified on tank to solution tank.	Burns, eye injury, chemical exposure	P.P.E., ventilation
2. Add specified amount of reverse osmosis water to solution tank to mix bleach.		Work by licensed mechanic.
		Follow manufacturer's instructions.