



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Removal of existing plumbing fixtures

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Mechanical Trades (Plumbing)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Coveralls, gloves, kneeling pads, kneepads, grade 1 safety footwear, safety glasses/goggles.

WESTERN HAZARD CATEGORY*

WorkSite/ Ergonomic Hazards

HAZARD TYPE*

Working alone, Projectiles, Sharp objects/ Weight

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

Plumbing/Fitting Shop

MGMT APPROVAL:

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Disconnect drain/water supply, remove brackets/ supports/fasteners	Inadequate space, sharp material, projectile	PPE, Proper lifting methods, assistance if possible/necessary/ use of lifting device
Lift/remove unit, fix/ repair location as required	Position, struck by/against, weight,	Work by licensed trades only
	Working alone	
Reference to		
*Wall-mounted urinals, counter sinks, floor mounted toilets, wall-mounted toilets, sloop sinks, laundry tubs, etc.	**Required safe use of power/hand tools.	