



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Sheet metal system/component installation (exterior)

DEPARTMENT

Physical Plant

WESTERN JOB CLASSIFICATION*

Mechanical Trades (acmf)

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Hearing protection (I.R.), hard hat (I.R.), knee pads, respiratory protection (I.R.), gloves, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

Worksite/ Physical Hazards

HAZARD TYPE*

Working at heights, Sharp objects, Struck by moving objects/ Noise

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ken Hill

REVIEWED BY:

ACMF Shop

MGMT APPROVAL:

Ken Hill

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Same as for interior	Position, fall, sharp material, slip/trip	PPE, co-worker assistance as required, proper lifting techniques
	Hand/power tools, noise, UV, burn, struck	Skin protection, appropriate clothing, clean work site
		Work by licensed mechanic.
*Installation of exterior systems/components		
*I.R. if required	*Required safe use of hand/power tools	