



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Use of 48" squaring shear

**DEPARTMENT**

Physical Plant

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (Acmf)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Grade 1 safety footwear, gloves, safety glasses/goggles

**WESTERN HAZARD CATEGORY\***

WorkSite Hazards

**HAZARD TYPE\***

Sharp objects, struck by moving object

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Place sheet on bench	Position, sharp material	Ensure no one near, PPE, check blade is clear
Slide onto table, step on treadle to cut material, remove. cut/leftover sheet.	Struck against/by.	Do not step on end of treadle, regularly clean up scrap, work by licensed mechanic