



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Use of power vise

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (Plumber, Steamfitter, Gas Technician)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Hearing protection, respiratory protection (I.R.), grade 1 safety footwear, protective clothing, gloves, protective clothing, 8271 mask safetyglasses/goggles

**WESTERN HAZARD CATEGORY\***

Physical/ WorkSite/ Equipment Hazards

**HAZARD TYPE\***

Noise/ Slips/Trips/Falls / Machinery

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

Plumbing/Fitting Shop

**MGMT APPROVAL:**

Dan Gyetvai

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Open clamping head, insert pipe/secure with clamp	Entanglement	PPE, use per manufacturer's instructions
Start unit *apply pipe cutter; tighten till cut, insert reamer to remove burrs	Sharp material	Keep work area clean
Start die/thread to depth/clean /release pipe from machine	Burn, projectile	Work by licensed trades
Clean machine and floor	Noise, struck against	
	Slip	
	Inhalation	
*Foot pedal operated		