



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Generator Check

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Generator Mechanic

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety boots, shoes, glasses, ear plugs

**WESTERN HAZARD CATEGORY\***

Physical Hazard

**HAZARD TYPE\***

Noise

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

T. McLennan

**REVIEWED BY:**

Motor Shop

**MGMT APPROVAL:**

Mike Howard

**SEQUENCE OF TASK**

**POTENTIAL HAZARDS**

**ACTION OR PROCEDURE**

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Notify CCPS	Noise exposure	Wear ear plugs
Switch generator to "off" position		
Check: battery/coolant/oil/hoses/belts etc.		
Switch generator back to auto as per transfer switch JHA		
Verify there are no alarms or warning conditions before leaving		