



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Paint Tinting

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety Glasses

WESTERN HAZARD CATEGORY*

Chemical/Worksite Hazards

HAZARD TYPE*

Other Liquids/Pinch Points

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Open can of paint	Spray of tint	Wear PPE
Place under tinting dispenser	Pinched skin	Consult book of directions on wall by paint tint dispenser
Add tint colours to paint		
Close lid on can		
Place in shaker		