



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Painting (Journey person)

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Journey person Painter

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Personal protective equipment

WESTERN HAZARD CATEGORY*

Ergonomic/Work Site hazards

HAZARD TYPE*

Repetitive Strain/Slips/Trips/Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Inspect work site, ID problems, risk assesment , safety concerns	Slips, trips, falls	Clear area to make safe worksite
Select appropriate supplies to complete task	improper material placement	Proper PPE and MSDS requirements
Moving heavy objects	muscle strain	Get help - lifting devices and procedures
Shake paint	Paint splatter, flyout of shaker	Ensure cans are secured properly in the shaker
Openings and closing paint cans	cuts, pinching	When closing cover top with rag and PPE
Scrape - repair sand	inhalation hazard, eye hazard	Try and change work task, eg., trade brush and roller work
Brush and roller work	repetitive injury	Switch tasks throught out day
Ladder for cutting and repairs	falls	safe ladder policy
