



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Using Latex and Oil Paints

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Painter

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Safety Footwear, Respirator (if required)

**WESTERN HAZARD CATEGORY\***

Ergonomic/Work Site Hazards

**HAZARD TYPE\***

Strain/Pinch Points, Slips/Trips/Falls

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ted Chelchowski

**REVIEWED BY:**

Structural Shop

**MGMT APPROVAL:**

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Mix can with machine	Paint spray	Wear PPE
Take materials to work area	Pinched skin	Bend knees when lifting
Prepare work area	Strained muscles	Use material carts
Paint areas	Breathing	Keep work area clean and ventilated
Use ladders when necessary	Falling or tripping	Use ladder safety
Clean up area		Wear dust masks or approved mask
Store paint properly		Cover unused paints
dispose of paint	spill hazard	use waste container in shop