

JOB HAZARD ANALYSIS - Task Specific

]NEW	x REVISED
WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD CA	TEGORY*	DATE:
Chain Saw Service/ Repairs	WorkSite Hazards	WorkSite Hazards	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Protruding/Sharp Obje	Protruding/Sharp Objects, Projectiles	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT	LOSS POTENTIAL RATING*	
Vehicle Mechanic	Low		Motor Shop
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Specif	ic Job Report	MGMT APPROVAL:
Safety Boots/Shoes, Glasses, Full face visor, Gloves, Ear muffs			Mike Howard
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE	
Remove plug wire	Projectile (moving parts)	Ensure proper ventilation	
Blow off dirt	Dust	Practice hand/power tool s	safety awareness
Check operation of:	Sharp Edges		
Chain Brake	Chemical		
Disassemble Chain			
End Bar			
Clean Internal Parts			
Check wear/ fit			
Repair/ sharpen blade			
Test			