

x REVISED

JOB HAZARD ANALYSIS - Task Specific

NEW

WORKPLACE TASK TO BE ANALYSED	WESTERN HAZARD C	WESTERN HAZARD CATEGORY*	
Service/Repair Push Lawnmowers	Worksite Hazards	Worksite Hazards	
DEPARTMENT	HAZARD TYPE*	HAZARD TYPE*	
Facilities Management	Struck by moving obje	Struck by moving objects	
WESTERN JOB CLASSIFICATION*	LOSS POTENTIAL RAT	LOSS POTENTIAL RATING*	
Vehicle Mechanic	Moderate	Moderate	
REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT	*refer to Stantec Speci	*refer to Stantec Specific Job Report	
Safety Boots/Shoes/Glasses/Gloves			Mike Howard
SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE	
Power wash unit	Sharp material	Secure and position equip repairs	oment appropriately for
Pull plug wire	Burns	Ensure proper ventilation	
Remove blade/ sharpen	Inhalation		
Drain oil/ remove plug	Struck by (moving parts)		
Clean air filter			
Replace oil/plug/blade			
Test			