

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure Oct 5, 2015 Time(s): 7:30am - 9:30am									
Building(s) #1 BIOTRON BUILDING (BIO) #2 #4 Areas/Rooms Affected Alternate Route/Service: Supply Fan systems 101 & 102-500.									
Service to be #1 Supply Air Fans #2 #4 Description/Reason for Project: Fan system 102 keeps tripping and one belt was missing. Replacing belts on both air handling units and will investigate the cause of the fan failure.									
Requester: Steve MacKay					Date of Request: Sep 30, 2015				
Supervising Tradesperson: Trade Supervisor: Steve MacKay				Motor	Date:Sep 30, 2015				
Contractor: Coordinator/Project Manager:				Phone #	Phone #				
Reviewed by Trade Supervisor(s)/Shop(s) Affected:									
Name:	WES Control	Date: Sep 30, 2015				Dat		e:	
Signature/ Stamp:	REVIEWED By Wayne Drummond (ppdwad@uwo.ca) at 11:21 am, Sep 30, 2015		Signature Stamp:	/					
Name:		Date:	Principal (Principal Occupants:					
Signature/			Name:			Ext.		Date:	
Stamp:			Name:	Name:		Ext.		Date:	
Name:		Date:	Name:			Ext.		Date:	
Signature/			Name:				Ext. Date:		
Stamp: Approval to Proceed: Date:								te:	
Name: Signature/ Stamp:	Pel By Dan Trudgeon (fminterr@uwo.ca) at 1:10 pm, Sep 30, 2015								
Notes:									