



**Notice of Service Interruption/Area Closure**  
**Western University**  
**Facilities Management**  
**Client Services 519-661-3304 (fmhelp@uwo.ca)**

Submit by E-mail  
 Print Form

Date of Interruption/Closure:  Time(s):

Building(s) Affected: #1  #2   
 #3  #4   
 Areas/Rooms Affected Alternate Route/Service:

Service to be interrupted: #1  #2   
 #3  #4   
 Description/Reason for Project:

Requester:  Date of Request:

Supervising Tradesperson:  Unit:   
 Trade Manager:  Unit:  Date:

Contractor:  Phone #   
 Coordinator/Project Manager:  Phone #  Date:

Reviewed by Trade Manager(s)/Shop(s) Affected:

Name: <input type="text" value="Electrical / Mechanical Shop"/>	Date: <input type="text" value="Jun 20, 2018"/>	Name: <input type="text" value="WES Control"/>	Date: <input type="text" value="Jun 20, 2018"/>
Signature/Stamp:		Signature/Stamp:	
Name: <input type="text"/>	Date: <input type="text"/>	Principal Occupants:	
Signature/Stamp: <input type="text"/>		Name: <input type="text"/>	Ext. <input type="text"/>
Name: <input type="text"/>	Date: <input type="text"/>	Name: <input type="text"/>	Ext. <input type="text"/>
Signature/Stamp: <input type="text"/>		Name: <input type="text"/>	Ext. <input type="text"/>
Name: <input type="text"/>	Date: <input type="text"/>	Name: <input type="text"/>	Ext. <input type="text"/>
Signature/Stamp: <input type="text"/>		Approval to Proceed: <input type="text"/>	
Name: <input type="text"/>	Date: <input type="text"/>		
Signature/Stamp: <input type="text"/>			

Notes:

# HAZARDOUS EXHAUST SYSTEMS INVENTORY

**LAST UPDATED : 2013 / 04 / 30**

BUILDING	DENTAL SCIENCE
----------	----------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
-003-	4028 A&B	K	K	Room Exhaust	1 ½" acetone exhaust
-006-	5006	K	K	Fume Cabinet	
-007-	5006	K	K	Fume Cabinet	
-008-	5005	K	K	Fume Cabinet	
-009-	5005	K	K	Fume Cabinet	
-014-	4035A	K	K	Fume Cabinet	Radio Isotope – stack
-019-	4032	Top of stair 6	Wall of roof E	Fume Cabinet	Louvre above E
-023-	0025	K	K	Fume Cabinet	
-032-	1008B	K	K	Hood	Switch Rm. 1008D
-033-	1008B	K	K	Hood	
-035-	2005	C	C	ELEPHANT TRUNKS PNL5P #3	
-036-	2005	C	C	ELEPHANT TRUNKS PNL5P #6	
-037-	2010B	C	C	DOUBLE Fume Cab PNL 5P #14	
-038-	2011	C	C	FUME CAB	PNL 5P #21
-039-	2011?	C	C	NOT SURE!	SHUTDOWN MAY6TH 2014.
-040-	2003	C	C	Fume Cab	
-042-	3003D	C	C	Fume Cab	
-044-	3003	C	C	Fume Cab	
-045-	3004	C	C	Fume Cab	
-046-	3004	C	C	Fume Cab	
-047-	3004	C	C	Fume Cab	
-049-	3005B	C	C	Fume Cab	
-051-	2006	C	C	Fume Cab	OUT OF SERVICE
-052-	3006B	C	C	Fume Cab	
-054-	3013	Top of stair 6	Wall of roof E	Fume Cab	Louvre Above E
-062-	4011	C	C	Fume Cab	
-064-	4014	C	C	Hood	
-065-	4015	C	C	Fume Cab	

-067-	5014	K	K	Solvent Room	
-068-	5001	K	K	Fume Cab	
-069-	5001	K	K	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS
-070-	4030	Top of stair 6	Wall of Roof E	Fume Cab	
-074-	5002A	K	K	LABELED ROOM EX NON HAZARDOUS?	
-078-	4010	C	C	Fume Cab	FC removed from rm 4009
-083-	3031	K	K	Fume Cab	Radioisotope Unit
-084-	2010G ???	E	E	Fume Cab	
-085-	2010G ???	E	E	Fume Cab	
-095-	6035	B	B	Cage Washer Ex.	
-096-	4034	K	K	Fume Cab	Radio Isotope stack
-097-	5004	K	K	Fume Cab	Radio Isotope stack
-007- 501	5000	K	K	1 Fume Cab 1 Fume Hood	

# HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING	HEALTH SCIENCE ADDITION
----------	-------------------------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
002	202	500	NORTH WALL	FUME CABINET	FED FROM MCC
003	216	500	NORTH WALL	FUME CABINET	FED FROM MCC
006	301F	C	C	FUME CABINET	FED FROM MCC <b>NEEDS NEW DOOR STICKER!</b>
007	408	C	C	FUM,E CABINET	FED FROM MCC
008	418	C	C	FUME CABINET	FED FROM MCC
009	418	C	C	HOOD	FED FROM MCC <b>SEE NOTE 3</b>
012	406	C	C	FUME CABINET	
013	415	C	C	FUME BENCH??	