



**Notice of Service Interruption/Area Closure**  
**Western University**  
**Facilities Management**  
**Client Services 519-661-3304 (fmhelp@uwo.ca)**

Submit by E-mail  
 Print Form

Date of Interruption/Closure:  Time(s):

Building(s) Affected: #1  #2   
 #3  #4

Areas/Rooms Affected Alternate Route/Service:  
 All rooms will be without domestic hot water.  
 Rooms 116, 216, 316, 416, 516 & 616 will be without domestic hot & cold water.

Service to be interrupted: #1  #2   
 #3  #4

Description/Reason for Project:  
 Leak on riser 16.  
 Leak on domestic heater 2.  
 Broken isolation valve on domestic heaters 1 & 2.

Requester:  Date of Request:

Supervising Tradesperson:  Unit:

Trade Manager:  Unit:  Date:

Contractor:  Phone #:

Coordinator/Project Manager:  Phone #:  Date:

Reviewed by Trade Manager(s)/Shop(s) Affected:

Name: <b>Housing</b>	Date: <b>Sep 27, 2016</b>	Name:	Date:
Signature/Stamp: <b>APPROVED</b> <i>By Chris Yeo (cyeo3@uwo.ca) at 4:25 pm, Sep 28, 2016</i>		Signature/Stamp:	
Name:	Date:	Principal Occupants:	
Signature/Stamp:		Name:	Ext. Date:
Name:	Date:	Name:	Ext. Date:
Signature/Stamp:		Name:	Ext. Date:
Name:	Date:	Name:	Ext. Date:
Signature/Stamp:		Approval to Proceed: <input type="checkbox"/> Date: <input type="text"/>	
Name:	Date:	<b>APPROVED</b> <i>By Dan Trudgeon (dtrudgeo@uwo.ca) at 2:26 pm, Sep 29, 2016</i>	
Signature/Stamp:			

Notes: Recirc pump on heater 2 started leaking, broke isolation valves trying to isolate to repair pump. Temporary patch on 116 should be fixed permanently with this shutdown.