

## Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure January 25 - February 1, 2017 Time(s): 7:00am, January 25th - 4:30pm, February 1st										ruary 1st	
Building(s) #1 MOLECULAR BIOLOGY LABORATORY (MBL) #2 Affected: #3 #4 Areas/Rooms Affected Alternate Route/Service: Rooms served by fan system 102 500											
Service to be #1 Return Air Fan #2 Fumehoods may alarm #3 Pressure differential possible #4 Description/Reason for Project:  Fan bearings are gone and require replacement. Supply air system 102 504 will continue to operate.											
Requester: Steve MacKay					Date of Request: Jan 24, 2017						
Supervising Tradesperson: Unit:											
Trade Supervisor: Steve MacKay					Unit:	Motor Shop Da			Date:Ja	Date:Jan 17, 2017	
Contractor:  Coordinator/Project Manager: Steve MacKay  Reviewed by Trade Supervisor(s)/Shop(s) Affected:					Phone # 88764				Date:Jan 17, 2017		
Name:	Steve MacKay		Date:	Na	me:		WES Control		Dat	e: Jan 24, 2017	
Signature APPROVED Stamp: By Steve MacKay at 2:24 pm, Jan 24, 2017					Signature/ Stamp: REVIEWED  By Jesse Atkinson (jatk)			in48@uwo.ca) at 3:41 pm, Jan 24, 2017			
Name:	I Date:										
Signature/				Name:			Ext.			Date:	
Stamp:					Name:		Ext.			Date:	
Name:	Name:			<u> </u>	ame:			Ext.		Date:	
Signature/ Stamp:					Approval to Proceed:			Ext.	Date:		
Name: Date:						APPROVED					
Stamp:  By Dan Trudgeon (dtrudgeo @uwo.ca) at 4:12 pm, Jan 24, 201									Jan 24, 2017		
Notes:											

