




Notice of Service Interruption/Area Closure Western University Facilities Management


Client Services 519-661-3304 (fmhelp@uwo.ca)


UNIVERSITY · CAN	NADA		31	abiliit by L-iliai	Fillitioniii
Date of Interr	uption/Closure 2/17/14 2/19/14	т	ime(s): 7:00am - 5:00pm		
	#1 Social Science Centre #3 sa Affected Alternate Route/Servi 0 will be shut down, yet turned of		#2 #4 #4 see attached floor plan that i	ndicates room	s and floors
	#1 Supply Air Fan #3 Reason for Project: er Coil Pan is leaking		#2 Return Air Fan		
Requester:	Ken Hill		Date of Reque	st: Jan 20, 2014	
Supervising	g Tradesperson:		Unit:		
Trade Supe	rvisor:		Unit:	Da	te:
	Great Lakes Mechanical roject Manager: Dean Brenan Trade Supervisor(s)/Shop(s) Affected	:	Phone # +1 (519) 808-		ate:
Name:	Ken Hill	Date:	Name: Electrical Mechanic	cal Shop	Date:
Signature/ Stamp:	APPROVED By ken hill (kenhill@uwo.ca) at 11:00 am,	Jan 20, 2014	Signature/ Stamp:		
Reviewed by	<i>r</i> :		Principal Occupants:		
Name:	Electrical Shop	Date:	Name:	Ext.	Date:
Signature/		JI	Name:	Ext.	Date:
Stamp:			Name:	Ext.	Date:
Approval to Pi	roceed: Date:	Appro	oval to Proceed: Date:		
			PROVED e Arbique (jarbique@uwo.ca) at	2:31 pm, Jan 2:	3, 2014
	ass Required by Electrical Shop and Tag out for AHU 103-500 b	y Motor shop			























				RU	OF SC	HEDUL	E				
LOCATION	AREA IN	YEAR	YEAR	ROOF DECK	VAPOUR	INSULATION		ROOF TYPE			REMARKS
	SQ. FT.	BULT	REDONE		BARRIER	TYPE	THICK	B.U.R.	I.R.M.A.	MEMBRANE	
AREA 'A'	1720	1971	1987	AS" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'B1'	4940	1971	1987	3" STEEL DECK	-		7	_	-	•	SARNAFIL ROOF
AREA '82'	1110	1971	1987	5" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA '83'	1250	1971	1987	7" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'C'	3140	1971	1987	8" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'D'	2720	1971	1987	8" CONC. SLAB	-		7	—	-	•	SARNAFIL ROOF
AREA 'E'	340	1971	1987	5" CONC. SLAB	-		7		-	•	SARNAFIL ROOF
AREA 'F'	480	1971		6" CONC. SLAB	-		7		·		
AREA 'G'	5340	1971		8" CONC. SLAB	-		7		·		
AREA 'H'	1250	1971		B* CONC. SLAB	۱ ۰ ۱		7	l	١.		ROOF UNDER CONC. FLOOR OF ANIMAL SHELTER
AREA 'JI'	350	1971	1988	3° COMP. DECK & 2 1/2° CONC.			7			•	SARNAFIL ROOF
AREA 'J2'	160	1971	1988	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'KI'	1810	1971		3" COMP. DECK & 2 1/2" CONC.			7		7		CONC. PAVERS & SAND OVER ROOF
AREA 'K2'	3280	1971	1995	3° COMP. DECK & 2 1/2° CONC.	•		2"			•	RUBBER TILES OVER SARNAFIL ROOF
AREA 'K3'	150	1971		3° COMP. DECK & 2 1/2° CONC.			7		- 7		CONC. SLAB OVER ROOF
AREA 'MT'	340	1971	1995	3° COMP. DECK & 2 1/2° CONC.	•		2"			•	SARNAFIL ROOF
AREA 'M2'	1010	1971	1995	5" CONC. SLAB	$\overline{}$		2"			•	SARNAFIL ROOF
AREA 'M3'	3910	1971	1979	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'M4'	820	1971	1979	3° COMP. DECK & 2 1/2° CONC.			7			•	SARNAFIL ROOF
AREA 'MS'	70	1971	1979	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'N1'	5810	1971	1980	3" STEEL DECK			7			•	SARNAFIL ROOF
AREA 'N2'	970	1971	1980	3" STEEL DECK			7			•	SARNAFIL ROOF
AREA 'N3'	490	1971	1980	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'P'	520	1971		6" CONC. SLAB			7		•		
AREA 'Q1'	1120	1971		3" STEEL DECK			7	•			
AREA 'Q2'	170	1971		5" CONC. SLAB			7				
AREA 'R1'	2320	1971		3° COMP. DECK & 2 1/2° CONC.			7		•		
AREA 'R2'	240	1971		6" CONC. SLAB			7		•		
AREA 'S'	5660	1971	1978	1 1/2" STEEL DECK	-		7			•	SARNAFIL ROOF
AREA 'TI'	600	1971		3" COMP. DECK & 2 1/2" CONC.	-		7				
AREA 'T2'	30	1971		6" CONC. SLAB			7				
AREA 'U1'	1680	1971		3" COMP. DECK & 2 - 4" CONC.			7		7		CONC. PAVERS OVER ROOF
AREA 'U2'	200	1971		6" CONC. SLAB			7		7		CONC. PAVERS OVER ROOF
AREA 'V'	2940	1971		9 - 11° CONC. SLAB			7			•	TUNNEL TO U.C.C. WATERPROOF MEMBRANE UNDER CONC. PA
-				i	-		-				
		-		t			-	-	-		

