




Notice of Service Interruption/Area Closure Western University Facilities Management


Client Services 519-661-3304 (fmhelp@uwo.ca)


UNIVERSITY · CANADA				Sub	mit by E-m	ail Print Form
Date of Interruption/Closure Feb	21, 2014		Time(s): 7	:30AM - 4:30PM		
Building(s) #1 Social Scien Affected: #3 Areas/Rooms Affected Altern AHU 104_500 Will be shut do affected.	nate Route/Servic		#2 #4 #4 ase see attach	ed floor plane that in	ndicates ro	oms and floors
Service to be #1 Supply Air I interrupted: #3 Description/Reason for Proje Repair to Chilled Water Pan t	ect:		#2 Rei	turn Air Fan		
Requester: Ken Hill				Date of Request:	Feb 20, 2014	4
Supervising Tradesperson Trade Supervisor:	:		Unit:			Date:
Contractor: Great Lakes Mech	ean Brenen			Phone # +1 (519) 808-46		Date:
Reviewed by Trade Supervisor(s) Name: Ken Hil		Date:	Name:	Electrical Mechanical	Shop	Date:
Signature/ Stamp:	ROVED		Signature/ Stamp:			
Reviewed by:			Principal C	Occupants:		
Name: Electrical Sh	пор	Date:	Name:		Ext.	Date:
Signature/			Name:		Ext.	Date:
Stamp:			Name:		Ext.	Date:
Approval to Proceed:	Date:		proval to Proce			
Notes: Bypass Required by Lock and Tag out for		y Motor Shop				























				RU	OF SC	HEDUL	E				
LOCATION AREA IN	YEAR		ROOF DECK	VAPOUR	INSULATION		ROOF TYPE			REMARKS	
	SQ. FT.	BULT	REDONE		BARRIER	TYPE	THICK	B.U.R.	I.R.M.A.	MEMBRANE	
AREA 'A'	1720	1971	1987	AS" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'B1'	4940	1971	1987	3" STEEL DECK	-		7	_	-	•	SARNAFIL ROOF
AREA '82'	1110	1971	1987	5" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA '83'	1250	1971	1987	7" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'C'	3140	1971	1987	8" CONC. SLAB	-		7	_	-	•	SARNAFIL ROOF
AREA 'D'	2720	1971	1987	8" CONC. SLAB	-		7	—	-	•	SARNAFIL ROOF
AREA 'E'	340	1971	1987	5" CONC. SLAB	-		7		-	•	SARNAFIL ROOF
AREA 'F'	480	1971		6" CONC. SLAB	-		7		·		
AREA 'G'	5340	1971		8" CONC. SLAB	-		7		·		
AREA 'H'	1250	1971		B* CONC. SLAB	۱ ۰ ۱		7	l	١.		ROOF UNDER CONC. FLOOR OF ANIMAL SHELTER
AREA 'JI'	350	1971	1988	3° COMP. DECK & 2 1/2° CONC.			7			•	SARNAFIL ROOF
AREA 'J2'	160	1971	1988	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'KI'	1810	1971		3" COMP. DECK & 2 1/2" CONC.			7		7		CONC. PAVERS & SAND OVER ROOF
AREA 'K2'	3280	1971	1995	3° COMP. DECK & 2 1/2° CONC.	•		2"			•	RUBBER TILES OVER SARNAFIL ROOF
AREA 'K3'	150	1971		3° COMP. DECK & 2 1/2° CONC.			7		- 7		CONC. SLAB OVER ROOF
AREA 'MT'	340	1971	1995	3° COMP. DECK & 2 1/2° CONC.	•		2"			•	SARNAFIL ROOF
AREA 'M2'	1010	1971	1995	5" CONC. SLAB	$\overline{}$		2"			•	SARNAFIL ROOF
AREA 'M3'	3910	1971	1979	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'M4'	820	1971	1979	3° COMP. DECK & 2 1/2° CONC.			7			•	SARNAFIL ROOF
AREA 'MS'	70	1971	1979	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'N1'	5810	1971	1980	3" STEEL DECK			7			•	SARNAFIL ROOF
AREA 'N2'	970	1971	1980	3" STEEL DECK			7			•	SARNAFIL ROOF
AREA 'N3'	490	1971	1980	5" CONC. SLAB			7			•	SARNAFIL ROOF
AREA 'P'	520	1971		6" CONC. SLAB			7		•		
AREA 'Q1'	1120	1971		3" STEEL DECK			7	•			
AREA 'Q2'	170	1971		5" CONC. SLAB			7	•			
AREA 'R1'	2320	1971		3° COMP. DECK & 2 1/2° CONC.			7		•		
AREA 'R2'	240	1971		6" CONC. SLAB			7		•		
AREA 'S'	5660	1971	1978	1 1/2" STEEL DECK	-		7			•	SARNAFIL ROOF
AREA 'TI'	600	1971		3" COMP. DECK & 2 1/2" CONC.	-		7				
AREA 'T2'	30	1971		6" CONC. SLAB			7				
AREA 'U1'	1680	1971		3" COMP. DECK & 2 - 4" CONC.			7		7		CONC. PAVERS OVER ROOF
AREA 'U2'	200	1971		6" CONC. SLAB			7		7		CONC. PAVERS OVER ROOF
AREA 'V'	2940	1971		9 - 11° CONC. SLAB			7			•	TUNNEL TO U.C.C. WATERPROOF MEMBRANE UNDER CONC. PA
-				i	-		-				
		-		t			-	-	-		

