

## Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

UNIVERSITY · CANADA	Submit by E-mail Print Form
Date of Interruption/Closure Mar 30, 2015	Time(s): 8:00am - 3:00pm
Building(s) #1 Talbot College #2 #4 #4 Areas/Rooms Affected Alternate Route/Service:  Rooms served by Fan 106, see attached HVAC drawings.	
Service to be #1 Supply Air Fan #2 #4 Description/Reason for Project:  Heating coil leaking, fitter and sheet metal mechanic need to enter ductwork to repair.	
Requester: P Dearing	Date of Request: Mar 30, 2015
Supervising Tradesperson: P Dearing Unit: Plumbing	
Trade Supervisor: Ken Hill	Unit: Sheet Metal Date:Mar 25, 2015
Contractor:  Coordinator/Project Manager:	Phone # Date:
Reviewed by Trade Supervisor(s)/Shop(s) Affected:	
Name: Electrical / Mechanical Shop Date: Mar 25, 201	Name: WES Control Date: Mar 25, 2015
Signature/ Stamp:  APPROVED  By Steve Pepper (spepper@uwo.ca) at 9:08 am, Mar 25, 2015	Signature/ Stamp:  REVIEWED  By Wayne Drummond (ppdwad@uwo.ca) at 8:21 am, Mar 25, 2015
Reviewed by:	Principal Occupants:
Name: ACMF Shop Date: Mar 25, 201	Name: Ext. Date:
	Name: Ext. Date:
Signature/ Stamp: APPROVED	Name: Ext. Date:
ATTIOVED	Name: Ext. Date:
Approval to Proceed: Date: Approval to Proceed: Date:	
APPROVED  By Dan Trudgeon (fminterr@uwo.ca) at 3:08 pm, Mar 25, 2015	
Notes:	





