

Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail
Print Form

Date of Interruption/Closure Mar 11, 2015 Time(s): 8:00-15:00							
Building(s) #1 THOMPSON ENGINEERING BUILDING (TEB) #2 #4 Areas/Rooms Affected Alternate Route/Service: There is the possibility of inconsistent air flow from AHUs 101_500, 102_500 and 103_500 while the control panels are being upgraded.							
Service to be #1 Supply Air Fan #2 Return Air Fan interrupted: #3 #4 Description/Reason for Project: Upgrading control panels for improved reliability and control.							
Requester: Kyle Smith				Date of Request: Mar 9, 2015			
Supervising Tradesperson: Rich Ramos Unit: Trade Supervisor: Doug Johnson Unit:				Date:			
Contractor: Coordinator/Project Manager: Reviewed by Trade Supervisor(s)/Shop(s) Affected:			Phone #	Date			
Name: Electrical / Control Shop	Date: March 9, 201	15 Name:		Date:			
Signature/ Stamp:		Signature/ Stamp:	REVIEWED				
Name: Principal Occupants:							
Signature/		Name:	Name:		Ext.		Date:
Stamp:	1	Name:			Ext.		Date:
Name:	Date: Name: Name:						Date:
Signature/ Stamp:			Approval to Proceed: Date:				
Name:	Date:						
Signature/ Stamp:							
Notes:							