



Notice of Service Interruption/Area Closure
Western University
Facilities Management
Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail

Print Form

Date of Interruption/Closure

Time(s):

Building(s) #1

#2

Affected:

#3

#4

Areas/Rooms Affected Alternate Route/Service:

2nd floor east reheat valves and perimeter heating

Service to be interrupted: #1

#2

#3

#4

Description/Reason for Project:

heat exchanger 4 leaking gasket
leak on line in room 39

Requester:

Date of Request:

Supervising Tradesperson:

Unit:

Trade Manager:

Unit:

Date:

Contractor:

Phone #

Coordinator/Project Manager:

Phone #

Date:

Reviewed by Trade Manager(s)/Shop(s) Affected:

Name: Date:

Name: Date:

Signature/
Stamp:

Signature/
Stamp:

REVIEWED

By Jesse Atkinson (jatkin48@uwo.ca) at 3:34 pm, Jul 04, 2016

Name: Date:

Principal Occupants:

Signature/
Stamp:

Name: Ext. Date:

Name: Ext. Date:

Name: Date:

Name: Ext. Date:

Name: Ext. Date:

Signature/
Stamp:

Approval to Proceed:

Date:

Name: Date:

Signature/
Stamp:

APPROVED

By Justin DeGurse (jdegurs3@uwo.ca) at 10:20 am, Jul 06, 2016

Notes: