



Notice of Service Interruption/Area Closure
Western University
Facilities Management
Client Services 519-661-3304 (fmhelp@uwo.ca)

Submit by E-mail

Print Form

Date of Interruption/Closure

Time(s):

Building(s) #1
Affected: #3

#2
#4

Areas/Rooms Affected Alternate Route/Service:

Dental Sciences Building - Equipment with Hazardous exhaust to roofs B C E F G H & K.
Health Sciences Addition - All fume hoods.

Service to be interrupted: #1
#3

#2
#4

Description/Reason for Project:

Review of work on roof B associated with the 6th floor lab project.

Requester:

Date of Request:

Supervising Tradesperson:

Unit:

Trade Manager:

Unit:

Date:

Contractor:

Phone #

Coordinator/Project Manager:

Phone #

Date:

Reviewed by Trade Manager(s)/Shop(s) Affected:

Name:

Date:

Name:

Date:

Signature/
Stamp:

APPROVED

Signature/
Stamp:

REVIEWED

By Jesse Atkinson (jatkin48@uwo.ca) at 11:02 am, Oct 18, 2017

Name:

Date:

Principal Occupants:

Signature/
Stamp:

Name:

Ext.

Date:

Name:

Name:

Ext.

Date:

Name:

Name:

Ext.

Date:

Signature/
Stamp:

Name:

Date:

Signature/
Stamp:

Approval to Proceed:

Date:

APPROVED

By Dan Trudgeon (dtrudgeo@uwo.ca) at 11:18 am, Oct 20, 2017

Notes:

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING	DENTAL SCIENCE
----------	----------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
-003-	4028 A&B	K	K	Room Exhaust	1 ½" acetone exhaust
-006-	5006	K	K	Fume Cabinet	
-007-	5006	K	K	Fume Cabinet	
-008-	5005	K	K	Fume Cabinet	
-009-	5005	K	K	Fume Cabinet	
-014-	4035A	K	K	Fume Cabinet	Radio Isotope – stack
-019-	4032	Top of stair 6	Wall of roof E	Fume Cabinet	Louvre above E
-023-	0025	K	K	Fume Cabinet	
-032-	1008B	K	K	Hood	Switch Rm. 1008D
-033-	1008B	K	K	Hood	
-035-	2005	C	C	ELEPHANT TRUNKS PNL5P #3	
-036-	2005	C	C	ELEPHANT TRUNKS PNL5P #6	
-037-	2010B	C	C	DOUBLE Fume Cab PNL 5P #14	
-038-	2011	C	C	FUME CAB	PNL 5P #21
-039-	2011?	C	C	NOT SURE!	SHUTDOWN MAY6TH 2014.
-040-	2003	C	C	Fume Cab	
-042-	3003D	C	C	Fume Cab	
-044-	3003	C	C	Fume Cab	
-045-	3004	C	C	Fume Cab	
-046-	3004	C	C	Fume Cab	
-047-	3004	C	C	Fume Cab	
-049-	3005B	C	C	Fume Cab	
-051-	2006	C	C	Fume Cab	OUT OF SERVICE
-052-	3006B	C	C	Fume Cab	
-054-	3013	Top of stair 6	Wall of roof E	Fume Cab	Louvre Above E
-062-	4011	C	C	Fume Cab	
-064-	4014	C	C	Hood	
-065-	4015	C	C	Fume Cab	

-067-	5014	K	K	Solvent Room	
-068-	5001	K	K	Fume Cab	
-069-	5001	K	K	Fume Cab	FLAMABLE MAT. CAB ENCLOSURE STILL EXISTS
-070-	4030	Top of stair 6	Wall of Roof E	Fume Cab	
-074-	5002A	K	K	LABELED ROOM EX NON HAZARDOUS?	
-078-	4010	C	C	Fume Cab	FC removed from rm 4009
-083-	3031	K	K	Fume Cab	Radioisotope Unit
-084-	2010G ???	E	E	Fume Cab	
-085-	2010G ???	E	E	Fume Cab	
-095-	6035	B	B	Cage Washer Ex.	
-096-	4034	K	K	Fume Cab	Radio Isotope stack
-097-	5004	K	K	Fume Cab	Radio Isotope stack
-007- 501	5000	K	K	1 Fume Cab 1 Fume Hood	

HAZARDOUS EXHAUST SYSTEMS INVENTORY

LAST UPDATED : 2013 / 04 / 30

BUILDING	HEALTH SCIENCE ADDITION
----------	-------------------------------

SYSTEM #	ROOM #	FAN LOCATION	OUTLET LOCATION	USE	NOTES
002	202	500	NORTH WALL	FUME CABINET	FED FROM MCC
003	216	500	NORTH WALL	FUME CABINET	FED FROM MCC
006	301F	C	C	FUME CABINET	FED FROM MCC NEEDS NEW DOOR STICKER!
007	408	C	C	FUME CABINET	FED FROM MCC
008	418	C	C	FUME CABINET	FED FROM MCC
009	418	C	C	HOOD	FED FROM MCC SEE NOTE 3
012	406	C	C	FUME CABINET	
013	415	C	C	FUME BENCH??	