



Notice of Service Interruption/Area Closure Western University Facilities Management

Client Services 519-661-3304 (fmhelp@uwo.ca)


Submit by E-mail
Print Form

										=
Date of Interrup	losure Jan 31, 2018	Time(s):	Time(s): 7:00 am - 2:00 pm							
	ted Alternate Route/Service	#2 #4 ason will shutd	own fan	101.]]		
Service to be #1 Supply Air Fan 101 #2 #3 #4 Description/Reason for Project: Repair heating coils in rooms.										
Requester:	lason \	Watkin				Date of Request:	Jan 29, 20)18		<u>]</u>
Supervising Tradesperson: Jason Watkin Unit: Steamfitter										
Trade Manag	Dan Gyetvai	Unit:	Unit: Steamfitter Date:Jan 29, 2018]		
Contractor:					Phone #					_
Coordinator/Project Manager:					Phone #			Date:		
Reviewed by Tra	ade Ma	nnager(s)/Shop(s) Affected:								_
Name:	Electri	ical / Mechanical Shop	Date:	Name:	Name: WES Control			Date:		
Signature/ Stamp:	APPROVED By spepper (spepper@uwo.ca) at 2:39 pm, Jan 29, 2018			Signature Stamp:	Signature/ Stamp: REVIEWED By Jesse Atkinson (jatkin48@uwo.ca) at 3:03 pm, Jan 29, 2018				2018	
Name:	ımber / Fitter Shop	Principal Occupants:								
	REVIEWED			Name:			Ext.		Date:	
Stamp:	By Dan Gye	etvai (dgyetvai@uwo.ca) at 3:04 pm, Jan 29, 2018	1-	Name:		Ext.		Date:		\rfloor
Name:			Date:	Name:	Name:		Ext.		Date:	4
Signature/ Stamp:					Approval to Proceed			Date:		_
Name: D			Date:	ADE	400001/50					
Signature/ Stamp:				APPROVED By Andrew Merucci (amerucci@uwo.ca) at 7:03 am, Jan 30, 2018						
Notes:										







THIRD FLOOR



SECOND FLOOR





PENTHOUSE FLOOR



4TH FLOOR

