

OHS Case ID: **8957FPRBKCR**
Field Visit no: **8957FPRBKCR-8957-FV001**

Visit Date: **2026-AUG-21**

Field Visit Type: **INITIAL**

Workplace Identification: **PK CONSTRUCTION INC.**
1393 WESTERN ROAD, LONDON, ON CA N6G 1G9

Notice ID: **26eN1012897**

Telephone: -

JHSC Status:
Active

Work Force #:
4

Completed %:
99

Persons Contacted: **Louise, KOZA Director of Health and Safety - Wellbeing**
Vesa, DANI Health and Safety Manager for Facilities Management
Elias, EL-ZOUKI Health and Safety Advisor
Darryl, STANLEY Service Mechanic

Visit Purpose: **Reactive: Event: 260715921**

Visit Location: **1400 Western Road, London - Social Sciences Bldg., Support Services Bldg., Boardroom**

Visit Summary: **No Orders Issued**

Detailed Narrative:

This Inspector attended the workplace in person to inspect for compliance with the Occupational Health and Safety Act (OHSA), 213/91 Ontario Construction Regulation (O.Reg.) and other related legislation in response to a complaint alleging the following:

"Social Sciences Building, 4th Floor, ACM exposure"

END OF REPORT.

DISCUSSIONS / FINDINGS BY THE MINISTRY OF LABOUR, IMMIGRATION, TRAINING AND SKILLS DEVELOPMENT.

This Inspector attended The University of Western Ontario regarding the allegations of Asbestos Exposure.

The Constructor is PK Construction, renovations had occurred in the Social Sciences Building, 4th floor.

Documents produced:

1. OH Solutions. (2025, June 16). *Designated substances survey: Social Sciences Centre, Suite 4200 renovations, Western University, London, Ontario* (Project No. 25-3630). Prepared for Western University Facilities Management.
2. Crisp Analytical, L.L.C. (2025, May 22). *Materials characterization: Bulk asbestos analysis, laboratory analysis report (polarized light)* (Customer Project No. 25-3630, SCC 4200 Suite WU). 6 pp.
3. OH Solutions. (2026, March 3). *Type 3 asbestos abatement clearance report: SCC 4200 Office Suite, Western University, London, Ontario* (Project No. 25-3630).
4. Pinchin Environmental. (2018, October). *Asbestos inventory: Western University, Social Sciences Centre* (revised ed.). Western University. 7 pp.

- The complainant is non-verifiable
- UWO Workers received Asbestos Awareness training
- Constructor has been provided with the above documents (not all-inclusive)

Case closed.

A COPY of this report is to be posted at the workplace.

Recipient		Inspector Data	Worker Representative	
Name	<u>Louise KOZA</u>	Kevin Johnston	Name	<u>[Signature]</u>
Title	<u>Director Health Safety + Wellbeing</u>	O.H.S.A. & B.O.S.T.A INSPECTOR PROVINCIAL OFFENCES OFFICER 4273 King St. E, #301, Kitchener, ON N2P 2E9 MOLOHSWaterloo@ontario.ca Tel: (519) 572-8522 Fax: (519) 883-5694	Title	<u>Worker Rep</u>
Signature	<u>[Signature]</u>	Signature	<u>[Signature]</u>	Signature

You are required under the Occupational Health and Safety Act to post a copy of this report in a conspicuous place at the workplace and provide a copy to the health and safety representative or the joint health and safety committee if any. Failure to comply with an order, decision or requirement of an inspector is an offence under Section 66 of the Occupational Health and Safety Act. You have the right to appeal any order or decision within 30 days of the date of the order issued and to request suspension of the order or decision by filing your appeal and request in writing on the appropriate forms with the Ontario Labour Relations Board, 505 University Ave., 2nd Floor, Toronto, Ontario M5G 2P1. You may also contact the Board by phone at (416) 326-7500 or 1-877-339-3335 (toll free), mail or by website at <http://www.olrb.gov.on.ca/> for more information.

The Government of Ontario wants to hear from you. You can provide feedback on this visit at 1-888-745-8888