

Due Date	Issue Date	Compliance #	OHS Insp.	Room	Building	Department
<b>Dec 29, 2011</b>	Dec 8, 2011	2011-3572	Mike	Periodical Room	Weldon Library	Weldon Library

**Description of Violation**

Sun work station cabling and power bar have come loose and are dangling. Originally secured using only clear box tape. Presents catch hazard.

**Action**

Please resecure. Consider a more 'secure' method than box tape

**Comments**

*Total Orders 614*